CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3008148
Transaction Date	19 Nov 2026, 16:42:44
Site Name	840 - Emirates Auctions
Transaction Number	81763828 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WDDHF8JB2F*******
Specification	Imported
Make	Mercedes
Model	E350
Model Year	2015
Color	White
Mileage	95858 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT RIGHT SIDE REPAIRED REPAINTED REFITTED,PORTION CRACK	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERED DIRTY PORTION GETTING RUSTY	الارضية
01.E Bumper	MINOR SCRATCHES	دعامية
01.F Bonnet	PORTION REPAIRED REPAINTED,REFITTED	غطاء المحرك
01.G Sign of front accident	FRONT BUMPERT FRAME , RADIATOR SUPPORT BULK HEAD , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED DIRTY CHCK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL PAN DENT , COMPONENTS REFITTED , PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Belt	FRONT RIGHT SIDE STUCK	حزام الأمان
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	COMPONENTS REFITTED , PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06.C Spare Tire &Tools	TIRE MISSING	الاطار الاحتياطي و العدة
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Suspension Subframe	REAR SUBFRAME PORTION BEND DENT	
08.B Other	SUSPENSION PARTS REFITTED	اخري
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودات
09.B Other	INNER COLUMN COVER REPAIRED	اخري
09.C Axle	FRONT LEFT HOUSING PORTION DAMAGED	اكسلات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER PORTION DAMAGED REPAIRED WORN OUT / INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
10.B AC Condition	OK,SWITCH PORTION FADED,REAR GRILL PORTION DAMAGED	المكيف
10.C Dash Board	STRIP LOOSE PORTION CRACK	لوحة القياده
10.D Steering Wheel and control buttons	ADJUSTMENT NOT WORKING PROPERLY	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae