



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>02 Jan 2022, 18:09:15</b>
Transaction Number	<b>50360582 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JN8BY2NYXJ9107943</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Patrol</b>
Model Year	<b>2018</b>
Color	<b>--</b>
Mileage	<b>163148 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Trunk	REPAINTED	صندوق
01.B Paint	PORTION REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Bumper	REPAINTED , MISALIGN & HAVE WINCH	دعامية
01.D Rusty	UNDER BODY PARTS , CHASSIS FRAME, SUSPENTION GETTING RUSTY	صدأ
<b>02 Seats Condition</b>		<b>المقاعد</b>
02.A Seat Condition	OK	حالة المقاعد
<b>03 Lights</b>		<b>الاضاءة</b>
03.A Head Light	OK	الاضاءة الرئيسية
<b>04 Wipers and Arms</b>		<b>المساحات</b>
04.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
<b>05 Interior Condition</b>		<b>الحالة الداخليه</b>
05.A AC Condition	OK	المكيف
05.B Mirror	OK	المرايا
<b>06 Chassis Condition</b>		<b>الشاصي</b>

DEFECT	REMARKS	
06.A Chassis	CHASSIS FRAME RUSTY	الشاسيه
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Engine Condition	MINOR LEAK	حالة المحرك
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box	OK	الجير
<b>09 Suspension System</b>		<b>ممتص الصدمات</b>
09.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
09.B Suspension Subframe	SUSPENSION SUBFRAME & CROSS MEMBER RUSTY	
<b>10 Steering Condition</b>		<b>المقود</b>
10.A Axel	BOTH SIDE BOOT DRY CRACK	اكسلات
<b>11 Brake Condition</b>		<b>الفرامل</b>
11.A Hand Brake	WEAK	فرامل اليد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.