



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 22 Jan 2023, 17:05:26 |
| Transaction Number | 17458008 (CC10006) | Queue Number | 657852 |



| | |
|------------------|--------------------------|
| Chassis Number | WVWEH21K9CW223732 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Volkswagen |
| Model | Golf GTI |
| Model Year | 2012 |
| Color | Black |
| Mileage | 0001 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 4 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|---|---------------------------|
| 01 Body | | جسم المركبة |
| 01.A Rusty | UNDER BODY ,SUSPENSION PARTS GETTING RUSTY . | صدأ |
| 01.B Floor | UNDER FLOOR COVERED ,CHECKED ONLY VISIBLE AREA . PORTION DENT . | الارضية |
| 01.C Sign of side accident | | وجود مؤشر لحادث في الجانب |
| 01.D Paint | BODY PORTION REPAIRED ,REPAINTED .MINOR DENTS SCRATCHES ON BODY . | الصبغ |
| 01.E Fenders | REAR RIGHT SIDE QUARTER PANEL DAMAGE . | مدكار |
| 01.F Vehicle Color | GRAY. | لون المركبة |
| 02 Tires and Rims Condition | | الاطارات |
| 02.A Rear Tyre | BOTH SIDE 2020 CRACKED . | الاطار الخلفي |
| 02.B Front Tyre | BOTHSIDE 2020 CRACKED . | الاطار الامامي |
| 03 Chassis Condition | | الشاسي |
| 03.A Chassis | CHECKED VISIBLE AREA OK. | الشاسيه |
| 04 Engine Condition | | المحرك |
| 04.A Visual Engine Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING & ENGINE PARTS MISSING . REFITTED OIL LEAK . | حالة المحرك النظري |

| DEFECT | REMARKS | |
|----------------------------------|----------------------------|------------------------|
| 05 Transmission Condition | | الجير |
| 05.A Road Test | NOT CHECKED . | فحص علي الطريق |
| 05.B Gear Box Mount | BUSHES CUT , | كرسي الجير |
| 05.C Visual Gear Box Condition | REFITTED OIL LEAK . | حالة الجير النظري |
| 06 Suspension System | | ممتص الصدمات |
| 06.A Arms | LOWER ARM BUSHES CRACKED . | ازرع |
| 06.B Shock Absorber | WEAK ,LEAK . | ممتص الصدمات |
| 07 Interior Condition | | الحالة الداخليه |
| 07.A AC Condition | NOT CHECKED . | المكيف |
| 07.B Odometer reading | NOT CHECKED . | قراءة عداد المسافات |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.