

Queue Number 2866294

Transaction Date 15 Oct 2026, 12:53:22

Site Name
840 - Emirates AuctionsTransaction Number
12911350 (CC10013) (CC10025)

Vehicle Details

Chassis Number	SALLMAM348*****
Specification	GCC Specification
Make	Range Rover
Model	Vogue
Model Year	2008
Color	Black
Mileage	132617 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION GETTING FADED	الصبغ
01.C Doors	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED PORTION REPAIRED , FRONT LEFT SIDE REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION RUST PROOFED REINFORCEMENT DENT	الارضية
01.F Bumper	MISALIGN , GRILL BRACKET DAMAGED LOOSE	دعامية
01.G Windshield	FRONT SPOT DENT	زجاج
01.H Bonnet	REPAINTED PORTION REPAIRED , REFITTED	غطاء المحرك
01.I Pillars	LEFT SIDE A/ PILLAR REPAIRED , B/ PILLAR COVER LOOSE	القوائم
01.J Trunk	INNER COVER PORTION DAMAGED LOOSE	صندوق
01.K Sign of front accident		وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS RUST PROOFED CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	VIN LAMINATED / DOOR POST STICKER WORN OUT	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Belt	FRONT RIGTH SIDE DAMAGED	حزام الأمان
04.B Seat Condition	WORN OUT BACK COVER LOOSE , SIDE COVER PORTION MISSING	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JEKRING , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B DIFFERENTIAL	MOUNT RUBBER DRY CRACK / FRONT REFITTED	الدفرنشل
05.C Road Test	NOT CHECKED	فحص علي الطريق
05.D Four Wheel Drive	NOT ENGAGED SWITCH DEFECTIVE	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACK	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2023 , RIGHT SIDE 2022 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
07.B Tail Light	BOTH SIDE PORTION CRACK	الضوء الخلفي
07.C Revers Light	COVER MISSING	نور الرجوع للخلف
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Hydraulic System	NOT WORKING PROPERLY (BODY LEVEL LOW)	النظام الهيدروليكي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09.B Axle	BOOT CUT	اكسلات
10 Interior Condition		الحالة الداخليه
10.A Other	CENTER CONSOLE BOX COVER DAMAGED , INTERIOR PARTS GETTING RUSTY	اخرى
10.B Mirror	LEFT SIDE FOLDING NOT WORKING LOOSE	المرايا
10.C AC Condition	OK , GRILL PANEL PORTION CRACK , REAR NOT WORKING	المكيف
10.D Roof Light	NOT WORKING PROPERLY	أنارة السقف
10.E Audio	SCREEN FADED	صوتيات
10.F Dash Board	WORN OUT PORTION DAMAGED	لوحة القيادة
10.G Roof Ceiling	LOOSE	بطانه السقف
10.H Sun Visor	LEFT SIDE BRACKET DAMAGED , RIGHT SIDE MIRROR LIGHT NOT WORKING PROPERLY	حاجب الشمس
10.I Door Panel	WORN OUT	لوحة بطانة الباب
10.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.K Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae