

Queue Number

2877742

Transaction Date

19 Oct 2026, 17:42:34

Site Name

840 - Emirates Auctions

Transaction Number

55698208 (CC10006) (CC10006)



Vehicle Details

Chassis Number	WDD2211711*****
Specification	Imported
Make	Mercedes
Model	S 500
Model Year	2006
Color	Silver
Mileage	22132 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR PORTION DENT ,MUDDY,,	صدأ
01.E Floor	UNDER FLOOR FULLY COVER	الارضية
01.F Fuel Tank	LEAKING	خزان الوقود

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FULLY COVERD, CHECKED VISIBLE AREA ONLY OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED	كرسي
03.B Other	OVER HEAT, OIL MIX	اخرى
03.C Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظرية للجير
04.B Gear Box Mount	BUSHES CRACKED	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE DAMAGED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACK WORN OUT	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	GETTING FADED	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	HYDRAULIC NOT WORKING	ممتص الصدمات
07.B Arms	BUSHES CUT	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Steering Boot	BOOT CUT	ربلة المقود
08.B Steering Box	LEAK	جهاز المقود
08.C Tie Rod End	BOOT CUT	مؤخرة الرودادات
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX BUTTON LOCK DAMAGED	اخرى
09.B AC Condition	LOW COOLING	المكيف
09.C Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.E Sunroof	CURTAIN PORTION LOOSE	فتحت سقف
10 Engine Cooling System		نظام تبريد المحرك
10.A Radiator Condition	OVER HEAT WATER MIX WITH OIL	حالة المبرد
10.B Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae