CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2937096
Transaction Date	02 Nov 2026, 14:28:49
Site Name	840 - Emirates Auctions
Transaction Number	29291967 (CC10010) (CC10010)



Vehicle Details

Chassis Number	MMM156FB1J*******
Specification	GCC Specification
Make	Chevrolet
Model	Trailblazer
Model Year	2018
Color	Grey
Mileage	130563 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED,	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES ,	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	MISALIGN ,SCRATCHES .	دعامية
01.F Trunk	REPAINTED PORTION REPAIRED.,STAY SHOCK WEAK	صندوق
01.G Sign of back accident		وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASIS FRAME GETTING RUSTY ,PORTION MINOR SPOT DENT.	الشاسيه
02.B Chassis Number	VIN AREA RUSTY.	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	COMPONENT PARTSCRUTY ,ABNORMAL NOISY ,MINOR OIL LEAK .	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	MINOR JERKING ,COMPONENT PARTS GETTING RUSTY.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2024.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024.	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Tail Light	LENS GETTING FADED.	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.,	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY.	اخري
09.B AC Condition	NOT COOLING.	المكيف
09.C Audio	CONTROL SWITCH MISSING	صوتيات
09.D Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae