



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>19 Aug 2022, 10:28:01</b>
Transaction Number	<b>39999956 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>KNAKU8112D5313821</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Kia</b>
Model	<b>Sorento</b>
Model Year	<b>2013</b>
Color	<b>Silver</b>
Mileage	<b>335879 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Rear Tyre	BOTH SIDE 2021/2020 CRACKED	الاطار الخلفي
01.B Front Tyre	BOTH SIDE 2017 EXPIRED	الاطار الامامي
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Bonnet	SHOCK WEAK.FADED	غطاء المحرك
02.B Trunk	SHOCK WEAK	صندوق
02.C Bumper	MISALIGN	دعامية
02.D Rusty	AVOID UNDER BODY PARTS GETTING RUSTY .	صدأ
02.E Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES & PORTION FADED	الصبغ
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	SIGN OF OIL WET.ABNORMAL NOISE.	حالة المحرك النظري
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Gear Box Mount	MOUNT CUT NOISY.	كرسي الجير
04.B Visual Gear Box Condition	OK	حالة الجير النظري
04.C Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
<b>05 Interior Condition</b>		<b>الحاله الداخليه</b>
05.A Mirror	LEFT SIDE LOOSE PLAY	المرايا
05.B AC Condition	NOT COOLING	المكيف
<b>06 Steering Condition</b>		<b>المقود</b>
06.A Axle	BAKLE BOOT CUT & AXLE MOUNT BRACKET LOOSE BOLT MISSING	اكسلات
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Arms	LOWER ARM BUSH CRACKED	ازرع
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Brake Light	REAR LEFT SIDE NOT WORKING	نور الفرامل
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.