CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2941216
Transaction Date	04 Nov 2026, 16:46:47
Site Name	840 - Emirates Auctions
Transaction Number	46793123 (CC10013) (CC10013)



Vehicle Details

Chassis Number	MMDAF26J2J*******
Specification	GCC Specification
Make	Mitsubishi
Model	Attrage
Model Year	2018
Color	Silver
Mileage	137827 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	3

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION CRACK	دعامية
01.E Fuel Tank	DENT	خزان الوقود
01.F Sign of front accident	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE CHASSIS ALIGN INNER DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS GETTING RUSTY DIRTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	DENT	اخري
06 Transmission Condition		الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	MINOR JERKING, PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B AC Condition	OK	المكيف
09.C Dash Board	GETTING FADED PORTION WORN OUT	لوحة القياده
09.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae