



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Jan 2023, 14:06:27
Transaction Number	65069367 (CC10009)	Queue Number	657502



Chassis Number	2C3CDXCT9FH880673
Engine Number	
Vehicle Class	Car
Manufacturer	Dodge
Model	Charger
Model Year	2015
Color	Silver
Mileage	119317 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	Imported

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	NOT CHECK/REFITTED	حالة الجير النظري
01.C Gear Box Mount	MOUNT CRACK	كرسي الجير
02 Suspension System		ممتص الصدمات
02.A Arms	LOWER ARM BUSH CRACKED	ازرع
02.B Ball Joint	BOOT CUT	مفصل كروي
03 Steering Condition		المقود
03.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	BOTH SIDE 2019 CRACKED,	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي
05 Body		جسم المركبة
05.A Sign of front accident		وجود مؤشر لحادث في المقدمة
05.B Sign of side accident		وجود مؤشر لحادث في الجانب

DEFECT	REMARKS	
05.C Bumper	MISALIGN/ FRONT CRACKED	دعامية
05.D Other	FRONT BUMPER FRAME BULK HEAD RADIATOR SUPPORT REPAIRED	اخرى
05.E Floor	PORTION DENT	الارضية
05.F Paint	BODY PORTION REPAIRED REPAINTED MINOR DENT SCRATCHES ON BODY	الصبغ
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
07 Engine Condition		المحرك
07.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,REFITTED	حالة المحرك النظرى
07.B Mount	MOUNT RUBBER CUT	كرسي
08 Interior Condition		الحالة الداخليه
08.A Dash Board	PORTION DAMAGED	لوحة القيادة
08.B Other	BOTH SIDE INNER PILLAR COVER LOOSE PARTS MISSING	اخرى
08.C AC Condition	NOT CHECKED	المكيف
09 Chassis Condition		الشاسي
09.A Chassis	FRONT RIGHT SIDE CHASSIS END REPAIRED , LEFT SIDE LOWER PORTION DENT	الشاسيه
09.B Chassis Number	MANUFACTUR STICKER MISSING	رقم القاعدة

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.