



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	07 Aug 2022, 13:39:34
Transaction Number	82373820 (CC10006)	Queue Number	312309



Chassis Number	6G1EK54U48L968425
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Lumina
Model Year	2008
Color	Black
Mileage	141930 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	NOT COOLING	المكيف
01.B Power Window Switch	REAR LEFT SIDE NOT WORKING	مفتاح النافذه
01.C Other	REMOT RUBBER WORN OUT	اخرى
01.D Door Panel	PORTION LOOSE	لوحة بطانة الباب
02 Tires and Rims Condition		الاطارات
02.A Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
02.B Rims Condition	RIMS HAVE DENT SCRATCHES	حالة الجنوط
02.C Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
03 Transmission Condition		الجير
03.A Gear Box Mount	MOUNT RUBBER CARCKED	كرسي الجير
03.B Visual Gear Box Condition	MINOR OIL LEAK, CLUTCH BEDAL LOOSE & REFITTED	حالة الجير النظري
03.C Road Test	NOT CHECK	فحص علي الطريق
04 Body		جسم المركبة
04.A Floor	UNDER FLOOR FENDER CHASSIS COVERED , CHECKED VISIBLE AREA	الارضية

DEFECT	REMARKS	
04.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
05 Steering Condition		المقود
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Indicator & Hazard light	REAR RIGHT SIDE NOT WORKING	الاشارات
07 Engine Condition		المحرك
07.A Visual Engine Condition	MINOR OIL LEAK REFITTED , SHAKING	حالة المحرك النظري
08 Chassis Condition		الشاصي
08.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
08.B Other	FOR RECHECK PROEPRLY REMOVE FENDER UNDER ENGINE COVERS	اخرى
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CUT	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.