



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **23 May 2023, 17:01:56**
 Transaction Number **30047750 (CC10010)** Queue Number **719195**



Chassis Number **WVWRV1AJ6FM200940**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Volkswagen**
 Model **Jetta**
 Model Year **2015**
 Color **Grey**
 Mileage **113740 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
01.B Bonnet	,REPAINTED ,REPAIRED.	غطاء المحرك
01.C Fenders	FRONT LEFT REPLACED ,RIGHT SIDE REPAIRED REPAINTED ,REFITTED ,	مدكار
01.D Sign of front accident		وجود مؤشر لحادث في المقدمة
01.E Sign of back accident		وجود مؤشر لحادث في الخلف
01.F Doors	LEFT SIDE REPAINTED ,REPAINTED ,FRONT RIGHT PORTION REPAINTED.	أبواب
01.G Bumper	MISALIGN ,PORTION DAMAGE.	دعامية
01.H Paint	BODY PORTION REPAIRED ,PORTION REPAINTED ,DENTS SCRATCHES ,PORTION FADED.	الصبغ
01.I Floor	UNDER FLOOR FULLY COVERED,CHECKED ONLY VISIBLE AREA. PORTION DENT.	الارضية
01.J Other	FRONT BONNET,BUMPER FRAME, REAR BUMPER FRAME REPAIRED.	اخرى

02 Tires and Rims Condition**الاطارات**

02.A Front Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2022 CRACKED .	الاطار الخلفي

DEFECT	REMARKS	
03 Interior Condition		الحالة الداخلية
03.A Roof Ceiling	LOOSE.	بطانه السقف
03.B Mirror	ADJUSTMENT SWITCHES MISSING.	المرايا
03.C AC Condition	NORMAL COOLING.	المكيف
03.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	JERKING.	حالة الجير النظرى
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Chassis Condition		الشاسي
05.A Chassis	REAR LEFT SIDE CHASSIS EXTESION END DENT ,CRASH BOX REPAIRED.	الشاسيه
06 Engine Condition		المحرك
06.A Visual Engine Condition	OIL LEAK ,MISFIRING ,ABNORMAL NOISY.	حالة المحرك النظرى
06.B Smoke	WHITE SMOKE.	دخان
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT & MESSAGE ON IN DISPLAY.	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	WEAK,LEAK.	ممتص الصدمات
08.B Arms	LOWER ARM BUSHES CRACKED .	ازرع
09 Brake Condition		الفرامل
09.A Hand Brake	WEAK.	فرامل اليد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.