

TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date 22 Sep 2021, 18:03:49

75832615 (CC10006) 312309 Transaction Number Queue Number



Chassis Number 2FMDK49C58BB37103 Engine Number Vehicle Class Car Manufacturer **Ford** Model Edge Model Year 2008 Red Color

Mileage

188326

DEFECT	REMARKS	
O1 Body		جسم المركبة
01.A Fenders	REAR BOTH SIDE REPAIRED, REPAINTED & FRONT RIGHT SIDE REPAINTED, LEFT SIDE REPLACED	مدكار
01.B Paint	BODY TOTALY REPAINTED ,PORTION REPAIRED EXCEPT TRUNK & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	REPAINTED	أبواب
01.D Bumper	REPAINTED	دعامية
01.E Roof	REPAINTED	السقف
01.F Bonnet	REPAIRED, REPAINTED	غطاء المحرك
01.G Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT REPAIRED	اخري
02 Chassis Condition		الشاصي
02.A Chassis	VISABLE AREA OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	SIGN OF LEAK	اخري
04 Transmission Condition		الجير
04.A Gear Box	ОК	الجير
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2017 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2017 CRACKED	الاطار الخلفي

DEFECT	REMARKS	
06 Lights		الاضاءة
06.A Head Light	ОК	الاضاءة الرئيسية
06.B Other	ОК	اخري
07 Brake Condition		الفرامل
07.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
07.B Break Pads	BRAKE WEAK	سفايف الرامل
08 Interior Condition		الاجزاء الداخلية
08.A Other	ОК	اخري
08.B Mirror	ОК	المرايا
08.C AC Condition	ОК	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.