CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2915209
Transaction Date	28 Oct 2026, 14:59:23
Site Name	840 - Emirates Auctions
Transaction Number	58117462 (CC10010) (CC10011)



Vehicle Details

Chassis Number	JNRAZ2NYXC*******
Specification	GCC Specification
Make	Infiniti
Model	QX 80
Model Year	2012
Color	Silver
Mileage	224065 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE,REAR LEFT REPAINTED PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED GETTING RUSTY	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	MISALIGN,PORTION CRACK	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Trunk	PORTION REPAIRED REPAINTED	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME RUSTY PORTION DENT ,MUDDY , OILY.	الشاسيه
02.B Chassis Number	VIN AREA GETTING RUSTY.	رقم القاعدة
03 Engine Condition		المحرك
03.A Smoke	WHITE SMOKE	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY,OVER HEAT, SIGN OF BURNING SMELL,	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED.	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES.	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED.	الاضاءة الرئيسية
07.B Warning Light	EXTRA WARNING LIGHT/WARNING MESSAGE ON IN CLUSTER	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	HARD ,WEAK ,	دواسة الفرامل
08.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CUT.	ازرع
09.C Stabilizer Bar And Link Rod	BUSHES CRACKED.	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Steering Boot	BOOT CUT .	ربلة المقود
10.B Steering Box	OIL LEAK ,HARD STEERING.	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX COVER WORN OUT,INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B Mirror	LOOSE	المرايا
11.C AC Condition	NO COOLING	المكيف
11.D Dash Board	LEATHER REPLACED PORTION LOOSE	لوحة القياده
11.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
11.H Engine Start Button	WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**