CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2972588
Transaction Date	11 Nov 2026, 17:03:06
Site Name	840 - Emirates Auctions
Transaction Number	96656195 (CC10009) (CC10019)



Vehicle Details

Chassis Number	JHMRC1852K*******
Specification	GCC Specification
Make	Honda
Model	Odyssey
Model Year	2019
Color	White
Mileage	412313 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR LEFT SIDE REPAINTED,PORTION REPAIRED,	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED, DENT SCRATCHES,PORTION FADED,MINOR RUSTY	الصبغ
01.C Doors	REAR RIGHT SIDE DOOR MAJOR DENT	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR COVERED PORTION DENT	الارضية
01.F Bumper	MISALIGN,PORTION CRACKED	دعامية
01.G Trunk	REPAINTED,PORTION REPAIRED,	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS MUDDY PORTION MINOR DENT GETTING RUSTY/OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Other	AIR INTAKE PIPE FIX BY TAP	اخري
03.B Engine Visual Condition	OIL LEAK PARTS REFITTED GETTING RUSTY MUDDY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 WORN OUT	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE PORTION CRACKED	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحاله الداخليه
08.A Other	INETRIOR PARTS GETTING RUSTY, SIGN OF FLODED	اخري
08.B Mirror	CENTER MIRROR PORTION FADED	المرايا
08.C AC Condition	OK	المكيف
08.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.E Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae