CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2986138
Transaction Date	14 Nov 2026, 11:23:44
Site Name	840 - Emirates Auctions
Transaction Number	24506048 (CC10009) (CC10019)



Vehicle Details

Chassis Number	JN8BY2NY9J*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2018
Color	White
Mileage	120563 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT LEFT SIDE ,REAR BOTH SIDE REPAINTED,PORTION REPAIRED,FRONT LEFT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	FRONT RIGHT SIDE & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN,GRILL PORTION DAMAGED	دعامية
01.F Trunk	AUTO SWITCH NOT WORKING PROPERLY DAMAGED	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD LEFT SIDE FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS GETTING RUSTY PORTION MINOR DENT/OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL WET PARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	EXTRA COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2024 & RIGHT SIDE 2021 EXPIRED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	BOTH SIDE BRACKET DAMAGED,REPAIRED	الاضاءة الرئيسية
07.B Fog light	LEFT SIDE NOT WORKING	كشاف الضباب
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
09 Steering Condition		المقود
09.A Steering Oil	MINOR OIL LEAK	زيت المقود
09.B Axle	RIGHT SIDE	اكسلات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX LEATHER PORTION LOOSE, INNER PARTS RUSTY	اخري
10.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae