

Queue Number

2836717

Transaction Date

05 Oct 2026, 15:44:57

Site Name

840 - Emirates Auctions

Transaction Number

16289423 (CC10009) (CC10012)



Vehicle Details

Chassis Number

WP1ZZZ92ZD*****

Specification

GCC Specification

Make

Porsche

Model

Cayenne GTS

Model Year

2013

Color

White

Mileage

139522 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY TOTALLY REPAINTED REPAIRED MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR CHASSIS NOT VISIBLE PROPERLY FULLY COVERED MUDDY	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Windshield	FRONT SPOT CRACKED	زجاج
01.F Door Handle & Lock	LEFT SIDE LOCK BUTTON MISSING	مقابض الأبواب والأقفال

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY COVER CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH REMOVE ALL UNDER COVER FOR RECHECK PROPERLY	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY, OVERHEAT	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	REFITTED OIL WET, MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE INNER COVER MISSING	الضوء الخلفي
07.C Indicator & Hazard light	FRONT BOTH SIDE PORTION CRACK	الاشارات
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	NOT COOLING , GRILL ADJUSTMENT PORTION MISSING	المكيف
08.C Power Window Switch And Glass	REAR LEFT SIDE NOT WORKING , CURTAIN NOT WORKING , BRACKET LOOSE	مفتاح النافذه و الزجاج
08.D Dash Board	LEATHER PORTION LOOSE	لوحة القيادة
08.E Roof Ceiling	PORTION LOOSE	بطانه السقف
08.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae