CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2877879 |
| Transaction Date | 20 Oct 2026, 10:42:09 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 55086671 (CC10021) (CC10019) |



**Vehicle Details**

| | |
|---|---|
| Chassis Number | 1FMEU73E18******* |
| Specification | GCC Specification |
| Make | Ford |
| Model | Explorer |
| Model Year | 2008 |
| Color | Blue |
| Mileage | N/A NA |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 6 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Paint | BODY REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES ,PORTION RUSTY PORTION FADED . | الصبغ |
| 01.B Floor | UNDER FLOOR,SUSPNSION NOT CHECK | الارضية |
| 01.C Bumper | MISALIGN PORTION DAMAGED. | دعامية |
| 01.D Roof | DAMAGED,HOLE RUSTY | السقف |
| 01.E Other | (VISUAL INSPECTION ONLY) | اخري |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | NOT CHECKED | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | ENGINE NOT START ALL SYSTEM NOT CHECK | الحالة النظريه للمحرك |
| **04 Seats Condition** | | المقاعد |
| 04.A Seat Condition | EXTRA COVER PORTION DAMAGED | حالة المقاعد |
| **05 Transmission Condition** | | الجير |
| 05.A Gear Box Visual Condition | NOT CHECKED | الحالة النظريه للجير |
| 05.B Road Test | NOT CHECKED | فحص علي الطريق |
| **06 Tires and Rims Condition** | | الاطارات |

| Condition | Remarks | الحالة |
|---|---|---|
| 06.A Front Tyre | CRACKED DAMAGED | الاطار الامامي |
| 06.B Rear Tyre | CRACKED DAMAGED | الاطار الخلفي |
| **07 Lights** | | الاضاءة |
| 07.A Head Light | LENS FADED,ALL LIGHT NOT CHECKED . | الاضاءة الرئيسية |
| 07.B Tail Light | LEFT SIDE DAMAGED | الضوء الخلفي |
| **08 Interior Condition** | | الحاله الداخليه |
| 08.A Other | INTERIOR PARTS RUSTY WATER FLOODED | اخري |
| 08.B Mirror | CENTER MIRROR FADED | المرايا |
| 08.C AC Condition | NOT CHECKED | المكيف |
| 08.D Dash Board | PORTION CRACKED DAMAGED | لوحة القياده |
| 08.E Roof Ceiling | PORTION LOOSE | بطانه السقف |
| 08.F Odometer reading | NOT CHECKED | قراءة عداد المسافات |
| 08.G Door Panel | PORTION DAMAGED,LOOSE | لوحة بطانة الباب |
| 08.H Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 08.I Gear Shifting Lever | KNOB WORN OUT | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae