

Queue Number 2840707

Transaction Date 06 Oct 2026, 15:01:00

Site Name
840 - Emirates AuctionsTransaction Number
87181229 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WP1ZZZ92ZE*****
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2014
Color	Black
Mileage	126499 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COVERED MUDDY OILY	الارضية
01.F Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COMPLETELY MUDDY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK REFITTED,SHAKING	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	OIL WET REFITTED, MINOR JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي

Condition	Remarks	الحالة
06 Lights الاضاءة		
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System ممتص الصدمات		
07.A Arms	BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition الحالة الداخلية		
08.A AC Condition	OK , GRILL ADJUSTMENT MISSING	المكيف
08.B Power Window Switch And Glass	REAR LEFT SIDE GLASS , CURTAIN NOT WORKING	مفتاح النافذه و الزجاج
08.C Dash Board	LEATHER REPLACED	لوحة القيادة
08.D Roof Ceiling	REPLACED	بطانه السقف
08.E Door Panel	LEFT SIDE LOOSE , WORN OUT	لوحة بطانة الباب
08.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.G Sunroof	NOT WORKING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae