CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906614
Transaction Date	27 Oct 2026, 15:17:23
Site Name	840 - Emirates Auctions
Transaction Number	70826490 (CC10021) (CC10021)

Vehicle Details

Chassis Number	1GKKVRKD2F*******
Specification	Imported
Make	GMC
Model	Acadia
Model Year	2015
Color	Black
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Doors	LEFT SIDE OUTER SKIRT MELTED	أبواب
01.C Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.E Bumper	MISALIGN , PORTION DAMAGE	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS GETTING RUSTY , PORTION DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED	اخري
10.B Mirror	LEFT SIDE SIDE VIEW MIRROR HOUSING MELTED	المرايا
10.C AC Condition	NOT CEHCK	المكيف
10.D Dash Board	PORTION WORN OUT	لوحة القياده
10.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae