



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 May 2023, 13:44:33
Transaction Number	75912989 (CC10008)	Queue Number	720945



Chassis Number	MDHBN7AD5DG025560
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Sunny
Model Year	2013
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
01.B Rear Tyre	BOTH SIDE 2016 EXPIRED,CRACKED	الاطار الخلفي
01.C Front Tyre	BOTH SIDE 2017 EXPIRED,DAMAGED	الاطار الامامي
02 Body		جسم المركبة
02.A Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
02.B Floor	PORTION DENT&BACK PANEL REPAIRED	الارضية
02.C Other	RUNNING BORAD DENT& LOWER RADIATOR SUPPORT BEND	اخرى
02.D Trunk	MODEL LOGO MISSING	صندوق
02.E Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES ,PORTION RUSTY	الصبغ
03 Lights		الاضاءة
03.A Head Light	LENS FADED,ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
04 Interior Condition		الحاله الداخليه
04.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

DEFECT	REMARKS	
04.B Power Window Switch	REAR LEFT GLASS DAMAGED,MISSING	مفتاح النافذه
05 Engine Condition المحرك		
05.A Mount	MOUNT BUSHES CRACKED	كرسي
05.B Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING,OIL WET ,REFITTED	حالة المحرك النظرى
06 Suspension System ممتص الصدمات		
06.A Coil Spring	COIL SPRING HEATED	ياي حلزوني
06.B Arms	LOWER ARM BUSHES CRACKED	ازرع
07 Transmission Condition الجير		
07.A Gear Box Mount	MOUNT BUSHES CRACKED	كرسي الجير
07.B Road Test	NOT CHECKED	فحص علي الطريق
07.C Visual Gear Box Condition	NOT CHECKED,OIL LEAK,REFITTED	حالة الجير النظرى
08 Chassis Condition الشاسي		
08.A Chassis	REAR CHASSIS EXTENSION END REAPIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.