

Queue Number 2861968

Transaction Date 12 Oct 2026, 16:56:29

Site Name
840 - Emirates AuctionsTransaction Number
90765562 (CC10026) (CC10026)

Vehicle Details

Chassis Number	JMYLRV93W9*****
Specification	GCC Specification
Make	Mitsubishi
Model	Pajero
Model Year	2009
Color	Black
Mileage	366182 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED REPAIRED , DENT SCRATCHES , PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PARTS MINOR DENT	الارضية
01.E Bumper	REAR BUMPER MISALIGN & FRONT BADLY DAMAGE	دعامية
01.F Bonnet	REFITTED , MISALIGN	غطاء المحرك
01.G Trunk	REFITTED , MISALIGN	صندوق
01.H Sign of front accident	BUMPER FRAME , INNER FENDER , RADIATOR SUPPORT BADLY BEND REPAIRED	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL , BUMPER FRAME REPAIRED , DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS END REPAIRED , DENT , GETTING RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECKED , PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT BOTH SIDE SEAT HAVE PLAY , EXTRA COVER DAMAGE	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير



Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED , PARTS REFITTED GETTING RUSTYSIGN OF OIL WET , MUDDY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2023 CRACK & RIGHT 2019 EXPIRED DAMAGE	الاطار الامامي
06.B Rear Tyre	REAR BOTH SIDE 2019 EXPIRED , DAMAGE	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
06.D Spare Tire &Tools	SPARE TIRE COVER PORTION DAMAGE	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	SIGN OF CRACK	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BOTH SIDE UPPER ARM REPAIRED & BUSHES CRACK	ازرع
09.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Steering Boot	BOOT CUT	ربلة المقود
10.B Steering Box	MINOR OIL LEAK	جهاز المقود
10.C Tie Rod End	BOOT CRACK	مؤخرة الروداد
11 Interior Condition		الحالة الداخليه
11.A Other	CENTER CONSOLE BOX DAMAGE PORTION LOOSE , INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
11.B Mirror	RIGHT SIDE VIEW MIRROR HOUSING LOOSE	المرايا
11.C AC Condition	AC NOT CHECK , GRILL DAMAGE , REAR AC DAMAGE	المكيف
11.D Power Window Switch And Glass	MAIN SWICTH PANEL PORTION CRACK	مفتاح النافذه و الزجاج
11.E Floor Matting	DIRTY	فرش الأرضيه
11.F Audio	CONTROL PANEL PORTION WORN OUT, DAMAGE , DISPLAY SCREEN FADED	صوتيات
11.G Dash Board	DAMAGE	لوحة القيادة
11.H Roof Ceiling	FABRIC LOOSE	بطانه السقف
11.I Sun Visor	BOTH SIDE LOOSE	حاجب الشمس
11.J Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.K Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.L Gear Shifting Lever	KNOB WORN OUT , SHIFTER SLIDER COVER MISSING	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك

Condition	Remarks	الحالة
12.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae