

Queue Number

2874214

Transaction Date

17 Oct 2026, 12:14:14

Site Name

840 - Emirates Auctions

Transaction Number

61817396 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JN8FY1NY6M*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2021
Color	Black
Mileage	103503 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION RUSTY	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR ALL BODY MOUNT REFITTED , PORTION DENT	الارضية
01.F Bumper	MISALIGN,SCRATCHES	دعامية
01.G Roof	PORTION REPAIRED REPAINTED	السقف
01.H Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.I Trunk	REPAINTED PORTION REPAIRED	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.K Vehicle Color	GRAY / BLACK	لون المركبة
01.L Vehicle Model	SAFARI	طرارز المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME REPAIRED THICK RUST PROOFED DENT BEND BULGED GETTING RUSTY	الشاسية
--------------	--	---------

03 Engine Condition

المحرك

03.A Smoke	MINOR WHITE	دخان
03.B Engine Visual Condition	ABNORMAL NOISY , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Belt	FRONT BOTH SIDE MISSING	حزام الأمان
04.B Seat Condition	FRONT BOTH SIDE LOOSE	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	DENT	اخرى
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECKED	فحص على الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2024 DRY CRACK	الاطار الخلفي
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Brake Condition		الفرامل
09.A Brake Pedal	HARD NOT WORKING PROPERLY	دواسة الفرامل
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	NO COOLING	المكيف
10.C Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING PROPERLY	مفتاح النافذه و الزجاج
10.D Dash Board	PORTION LOOSE,LEATHER REFITTED,VIN PLATE REFITTED	لوحة القيادة
10.E Steering Wheel and control buttons	GETTING WORN OUT,HARD	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB GETTING WORN OUT,4WD LEVER DUST COVER LOOSE	ذراع نقل السرعات
10.G Engine Start Button	STARTING PROBLEM DELAY STARTING	زر تشغيل المحرك
11 Battery Condition		حالة البطارية
11.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae