



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Jul 2022, 16:59:00
Transaction Number	55562571 (CC10006)	Queue Number	312309



Chassis Number	1ZVFT82H955165054
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Mustang
Model Year	2005
Color	Red
Mileage	100243 Miles
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.B Bonnet	MODIFIED & BONNET HAVE EXTRA LOCK	غطاء المحرك
01.C Pillars	RIGHT SIDE DOOR PILLAR REPAIRED	القوائم
01.D Other	FRONT FENDER FRAME RADIATOR SUPPORT ,BULK HEAD ,BUMPER FRAME REPAIRED	اخرى
01.E Floor	RIGHT SIDE RUNNING BOARD, QUATER PANEL REPAIRED	الارضية
02 Engine Condition		المحرك
02.A Visual Engine Condition	ENGINE MODIFIED WITH SUPERCHARGER	حالة المحرك النظري
02.B Modification	AIR FILTER MODIFIED	تعديلات
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	OIL LEAK&GEAR NOT PROPERLY HARD SHAFTING	حالة الجير النظري
03.B Road Test	NOT CHECK	فحص علي الطريق
04 Suspension System		ممتص الصدمات
04.A Ball Joint	BOOT CUT	مفصل كروي

DEFECT	REMARKS	
04.B Arms	LOWER ARM BUSHES CRACKED	ازرع
05 Engine Cooling System		نظام تبريد المحرك
05.A Radiator Condition	MODIFIED	حالة المبرد
05.B Coolant tank	MODIFIED	خزان التبريد
06 Interior Condition		الحالة الداخلية
06.A Door Panel	PORTION DAMAGED & LOOSE	لوحة بطانة الباب
07 Chassis Condition		الشاسي
07.A Chassis	FRONT BOTH SIDE CHASSIS MINOR BEND	الشاسيه
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09 Exhaust System		نظام العادم
09.A Modification	CATAYLIC CONVERTER MISSING , MODIFIED NOSIY	تعديلات
10 Tires and Rims Condition		الاطارات
10.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
10.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Change possession :	65887573
Chassis No :	1ZVFT82H955165054
Vehicle Make :	FORD
Vehicle Model :	MUSTANG
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Red
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	161327 Kms.
Origin : United States	Model Year : 2005
Gear Type : Manual	Engine Size : 5000 CC
Engine No : NIL	Horse 300
Axles No : 2	Power :
No Of 2	Cylinders : 8
Doors :	No Of Seats : 4
G. V. W. : 2141 Kgs.	Empty 1652 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17310607	
Inspection Date :	31-07-2022	
Certificate Print Date :	31-07-2022	
Services :	Registration Test	
Vehicle Testing Partner :	Tasjeel	
Vehicle Testing Center :	Tasjeel Al Aweer	
Total Time Taken :	19 min 51 sec	
Appointment Ref Number :	--	
Start Time :	18:08	End Time : 18:28
Lane :	01	Token No. : 192
Attempt : 1		Prints No : 1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
9 %	5 %	8 %	0.82 %
Vehicle on Petrol HC Reading			
124 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Exhaust pipes and silencers muffler EXHAUST MODIFIED&NOISY /FIX ORIGINAL	Others (Major)	Major
Spare Tire FIX SPARE TIRE	Missing (Major)	Major
Gear/Differential REPAIR GEAR OIL LEAK	Others (Major)	Major
Front and Rear Windshields CHANGE FRONT WIND SHIELD CRACK	Front Cracked/broken (Major)	Major
Engine FIX ORIGINAL ENGINE / MOUNTING MODIFIED WITH EXTRA SUPER CHARGE	Modified	Major
Bumper FIX PROPERLY FRONT BUMPER&LEFT SIDE INDICATOR	Unsecure	Major
Engine REPAIR ENGINE OIL LEAK	Others (Major)	Major

Inspection Remarks:

FRONT LEFT SIDE CHASSIS END,FENDER FRAME,BULK HEAD AND RIGHT SIDE B PILLAR,WHEEL ARC&REAR LEFT SIDE QUARTER PANEL&BUMPER OLD REPAIRED,,,,

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
3104	VTP Credit Account	17310607	AED 170 Collected on 31/07/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including



selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.