



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **06 May 2022, 11:34:37**
 Transaction Number **73357465 (CC10008)** Queue Number **312309**



Chassis Number **WBA3A5G58FNS82714**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **BMW**
 Model **328i**
 Model Year **2015**
 Color **Blue**
 Mileage **25053 Miles**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **USA Imported**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Windshield	FRONT CRACKED	زجاج
01.B Fenders	REPAINTED PORTION REPAIRED ,FRONT REFITTED	مدكار
01.C Paint	BODY REPAINTED ,PORTION REPAIRED & DENTS, SCRATCHES ON BODY	الصبغ
01.D Bonnet	REPAINTED	غطاء المحرك
01.E Doors	LEFT SIDE DOOR REPAINTED	أبواب
01.F Bumper	FRONT LOOSE & MISALIGN	دعامية
01.G Floor	FRONT FLOORING COVER DAMAGED	الارضية
01.H Other	REAR BOTH SIDE QUARTER PANEL REPAIRED, FRONT LEFT SIDE BULK HEAD REFITTED	اخرى
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK	المكيف
02.B Door Panel	COVER PORTION DAMAGED	لوحة بطانة الباب
02.C Power Window Switch	REAR LEFT SIDE NOT WORKING	مفتاح النافذه
03 Lights		الاضاءة
03.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير

DEFECT	REMARKS	
03.B Fog light	LEFT SIDE MISSING	كشاف الضباب
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Steering Condition		المقود
05.A Steering Oil	MINOR OIL LEAK	زيت المقود
06 Suspension System		ممتص الصدمات
06.A Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2017 EXPIRED , WORN OUT	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2017 EXPIRED , WORN OUT	الاطار الخلفي
08 Engine Condition		المحرك
08.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
09 Chassis Condition		الشاسي
09.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.