



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **08 Nov 2022, 17:52:06**
 Transaction Number **91790909 (CC10009)** Queue Number **619824**



Chassis Number **MNTBC2C91G6009652**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Nissan**
 Model **Tiida**
 Model Year **2016**
 Color **White**
 Mileage **216375 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	REVERCE GEAR DELAY SHIFTING, SIGN OF MINOR OIL LEAK	حالة الجير النظري
01.C Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
02 Body		جسم المركبة
02.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
02.B Sign of back accident		وجود مؤشر لحادث في الخلف
02.C Floor	BACK PANEL , SPARE WHEEL HOUSING, COMPARTMENT , QUATER PANEL REPAIRED	الارضية
02.D Bumper	MISALIGN	دعامية
02.E Sign of front accident		وجود مؤشر لحادث في المقدمة
02.F Fuel Tank	FUEL DRIPPING	خزان الوقود
03 Interior Condition		الحالة الداخلية
03.A AC Condition	OK	المكيف
04 Tires and Rims Condition		الاطارات

DEFECT	REMARKS	
04.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
05 Engine Condition		المحرك
05.A Smoke	MINOR WHITE SMOKE	دخان
05.B Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
06 Chassis Condition		الشاسي
06.A Chassis	REAR LEFT SIDE CHASSIS EXTENSION END REPAIRED	الشاسيه
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CRACKED	مفصل كروي
08 Lights		الاضاءة
08.A Other	REAR NUMBER PLATE LIGHT PANEL COVER MISSING	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.