



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 19766632	Plate Category	: PRIVATE
Transaction Date	: 12 MAY 2020 10:11:36	Plate Number	: 50528 EA
Queue Number	: 176951	Import Doc. Ref.	:
Chassis Number	: 2LNBL8CV1BX750528	Manufacturer/Model	: LINCOLIN/TOWN
Engine Number	:	Model Year	: 2011
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية TIRES 2017 & PUNCTURE (ROAD TEST NOT DONE)
05 Body		الهيكل
05.03 - Doors		الابواب REAR LEFT DOOR PILLAR REPAIRED
05.07 - Floor		الارضية MIDDLE FLOORING /REINFORCEMENT & BOTH SIDE RUNNING BOARD REPAIRED
05.08 - Chassis (Frame)		الشاصية CHASSIS FULL RUSTY & PAINTED & REAR LEFT DENT
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي FRONT REPLACED
05.10 - All Glasses		الزجاج الجانبي وزجاج الابواب FRONT RIGHT WINDOW NOT FUNCTION & MAIN POWER WINDOW SWITCH DEFECTIVE
06 General Items		الاشياء العامة
06.14 - Transmission Condition		حالة ناقل الحركة OIL LEAK
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى 230728 MILES
09 Auction		الفحص الكامل
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة REAR LEFT QUARTER PANEL REPAIRED
09.24 - Digital Display Damaged/Warning Lights		عطل في لوحة التحكم الالكتروني TIRE PRESSURE & AIR BAG LIGHT ON
09.25 - Body Repainted		أثر صيغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

# Test Certificate



PASS

Possession Certificate :	64271363
Chassis No :	2LNBL8CV1BX750528
Vehicle Make :	LINCOLN
Vehicle Model :	TOWN CAR
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	371320 Kms.
Origin :	United States
Model Year :	2011
Gear Type :	--
Engine No :	NIL
Engine Size :	4600 CC
Axles No :	2
Horse Power :	239
No Of Doors :	4
G. V. W. :	2400 Kgs.
Cylinders :	8
No Of Seats :	5
Empty Weight :	1500 Kgs.

Certificate Number :	5-TAS-2020-11978171
Inspection Date :	14-05-2020
Certificate Print Date :	14-05-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	11 min 57 sec
Appointment Ref Number :	--
Start Time :	13:26
End Time :	13:38
Lane :	01
Token No. :	3
Attempt :	1
Prints No :	1

## Carbon footprint



Keep protecting Dubai environment

## Estimated Vehicle Consumption ( Rate last 12 Months )

28257 KM	2908 L	4711 AED	7.0 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 9 %	Service brake imbalance on rear axle 19 %	Parking brake imbalance between LHS and RHS 18 %	Vehicle on Petrol CO Reading 0.62 %
--	--	---	--

Vehicle on Petrol HC Reading  
91 PPM VOL

## Inspection Remarks:

REAR LEFT QUARTER PANEL .RUNNING BOARD /MIDDLE FLOORING REPAIRED CHASSIS RUSTY & PAINTED & REAR LEFT DENT

## Payment Details

Inspection Performed by 59460	Payment Method VTP Credit Account	Transaction Number 11978171	Service Fees AED 170 Collected on 14/05/2020
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Raul Canceran Galang

① This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء ماملة واحدة فقط خلال 30 يوم من تاريخ الفحص . المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and

