



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 Oct 2021, 17:43:00</b>
Transaction Number	<b>19954856 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WDDKJ5GB5BF098149</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>E 350</b>
Model Year	<b>2011</b>
Color	<b>White</b>
Mileage	<b>104993 N/A</b>

DEFECT	REMARKS	
<b>01 Chassis Condition</b>		<b>النشاصي</b>
01.A Chassis	VISABLE AREA OK	النشاصيه
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Other	MINOR OIL LEAK&NOISY	اخرى
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Gear Box	OK	الجير
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED	الصبغ
04.B Fenders	REAR BOTH FENDER REPAIRED,REPAINTED&FRONT FENDER REPAINTED,REFITIED	مدكار
04.C Doors	REPAINTED	أبواب
04.D Bumper	REPAINTED&FRONT BUMPER FRAME MINOR DENT	دعامية
04.E Bonnet	REAR TRUNK REPAINTED	غطاء المحرك
04.F Pillars	RIGHT B/PILLAR ,ROCKER PANEL REPAIRED	القوائم
04.G Floor	UNDER BODY FULLY COVERED,VISBALE AREA CHECK ONLY	الارضية
04.H Other	INNER DOOR PADS COVER DAMAGED	اخرى
04.I Roof	SUNROOF CURTAIN MISSING	السقف
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH 2020	الاطار الامامي

DEFECT	REMARKS	
05.B Rear Tyre	BOTH 2020	الاطار الخلفي
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Shock Absorber	FRONT BOTH LEAK	ممتص الصدمات
<b>07 Seats Condition</b>		<b>المقاعد</b>
07.A Other	OK	اخرى
<b>08 Wipers and Arms</b>		<b>المساحات</b>
08.A Other	WORN OUT	اخرى
<b>09 Interior Condition</b>		<b>الاجزاء الداخلية</b>
09.A AC Condition	OK	المكيف
09.B Other	CONSOLE BOX SLIDING COVER DAMAGED	اخرى
<b>10 Lights</b>		<b>الاضاءة</b>
10.A Head Light	OK	الاضاءة الرئيسية
<b>11 Exhaust System</b>		<b>نظام العادم</b>
11.A Other	OPEN&REWELDED	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.