

Queue Number 2783802

Transaction Date 21 Sep 2026, 17:01:22

Site Name
840 - Emirates AuctionsTransaction Number
12437235 (CC10009) (CC10012)

Vehicle Details

Chassis Number	JMYLYV95WF*****
Specification	GCC Specification
Make	Mitsubishi
Model	Pajero
Model Year	2015
Color	Grey
Mileage	180664 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED MINOR DENT SCRATCHES	الصبغ
01.B Doors	RIGHT SIDE BOTH REPAINTED , REAR , REFITTED	أبواب
01.C Rusty	UNDER BODY CHASSIS SUSPENSION ENGINE GEAR RUSTY	صدأ
01.D Floor	FLOOR MUDDY PORTION DENT	الارضية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION COVERED OILY MUDDY ,VISIBLE AREA /OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK PARTS REFITTED , ENGINE RUSTY MUDDY , SHAKING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS REFITTED RUSTY , JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	RIGHT SIDE 2024 , LEFT SIDE 2020 EXPIRED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020 EXPIRED	الاطار الخلفي

06 Lights

الاضاءة

Condition	Remarks	الحالة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Fog light	BUTTON LOOSE	كشف الضباب
07 Suspension System		ممتص الصدمات
07.A Other	SUSPENSION GETTING RUSTY	اخرى
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR REFITTED , (INTERIOR PARTS RUSTY , WATER FLOODED)	اخرى
08.B Mirror	LEFT SIDE FOLDING NOT WORKING , LOOSE	المرآيا
08.C AC Condition	NOT COOLING	المكيف
08.D Roof Light	LIGHT COVER PORTION LOOSE	أنارة السقف
08.E Dash Board	PORTION CRACK	لوحة القيادة
08.F Odometer reading	DISPLAY MINOR FADED	قراءة عداد المسافات
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	DUST COVER MISSING	ذراع نقل السرعات
09 Battery Condition		حالة البطارية
09.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae