

Queue Number	2877706	Transaction Date	19 Oct 2026, 17:42:32
Site Name	840 - Emirates Auctions	Transaction Number	87648799 (CC10006) (CC10006)
		Vehicle Details Chassis Number KL8CB6SA1G***** Specification Imported Make Chevrolet Model Spark Model Year 2016 Color Blue Mileage 227308 Miles Fuel Type Petrol Transmission Type No. Of Cylinders 4	

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED, REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY,	الصبغ
01.C Doors	PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	BACK PANEL REPAIRED, UNDER FLOOR RUST PROOFED, PORTION FDENT, PORTION RUSTY	الارضية
01.F Bumper	PORTION REPAINTED, PORTION REPAIRED	دعامية
01.G Other	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	اخرى
01.H Sign of front accident		وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاسي
02.A Chassis	FRONT BOTH SIDE END REPAIRED, LEFT SIDE OPEN, DETACHED	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED	كرسي
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING PARTS RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظرية للجير

Condition	Remarks	الحالة
04.B Gear Box Mount	BUSH CRACKED	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE CRACKED	الاطار الخلفي
06 Suspension System		ممتص الصدمات
06.A Arms	BUSHES CRACKED	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
07 Interior Condition		الحاله الداخليه
07.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخرى
07.B Door Panel	PORTION CRACKED	لوحة بطانة الباب
07.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae