





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 23732892	Plate Category	: PRIVATE
Transaction Date	: 21 JAN 2021 10:03:37	Plate Number	: 331483 EA
Queue Number	: 285210	Import Doc. Ref.	:
Chassis Number	: WDDKJ6FB2GF331483	Manufacturer/Model	: MERCEDES/E 400
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.04 - Head Lights		الانوار الامامية LEFT SIDE HEAD LIGHT BRACKET & HOUSING REPAIRED & CORNER CRACK
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية FRONT 2016 & 2018
04.04 - Rear Left And Right Hand Tires		الاطارات الخلفية REAR 2015 & 2018
04.07 - Rims		الرنجات SCRATCHES
05 Body		الهيكل
05.02 - Paint		الصينغ BODY MINOR SCRATCHES & DENTS
05.04 - Fenders		المدكار LEFT SIDE FENDERS REPAIRED
05.05 - Bumpers		الدعامية FRONT BUMPER SUPPORT FRAME CRACK & CRASH BOX DENT/BUMPER REPLACED
05.10 - All Glasses		الزجاج الجانبي وزجاج الابواب REAR LEFT SIDE WINDOW NOT CLOSING PROPERLY
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى 33160 MILES
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		يحتاجه الى ميزانية العجلات
09.06 - Chassis Ok	OK	الشاصي جيد
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة BULKHEAD RE-FITTED
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.24 - Digital Display Damaged/Warning Lights		عطل في لوحة التحكم الالكتروني AIR BAG LIGHT ON



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 23732892	Plate Category	: PRIVATE
Transaction Date	: 21 JAN 2021 10:03:37	Plate Number	: 331483 EA
Queue Number	: 285210	Import Doc. Ref.	:
Chassis Number	: WDDKJ6FB2GF331483	Manufacturer/Model	: MERCEDES/E 400
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

#### Statement of Vehicle Condition

09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئول عن العيوب الخفية</p>		

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	--
Chassis No :	WDDKJ6FB2GF331483
Vehicle Make :	MERCEDES
Vehicle Model :	E CLASS
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	53364 Kms.
Origin :	Germany
Model Year :	2016
Gear Type :	--
Engine Size :	4700 CC
Engine No :	NIL
Horse Power :	--
Axles No :	2
Cylinders :	6
No Of Doors :	2
No Of Seats :	4
G. V. W. :	Empty Weight : 1240 Kgs. 1870 Kgs.

Certificate Number :	5-MUT-2021-13407738
Inspection Date :	18-01-2021
Certificate Print Date :	18-01-2021
Services :	Registration Test
Vehicle Testing Partner :	Al Mutakamela Vehicle Testing LLC
Vehicle Testing Center :	Al Mutakamela Vehicle Testing Al Qouz
Total Time Taken :	11 min 23 sec
Appointment Ref Number :	--
Start Time :	12:48
End Time :	12:59
Lane :	09
Token No. :	317
Attempt :	1
Prints No :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)

20 KM	3 L	5 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 10 %	Service brake imbalance on rear axle 4 %	Parking brake imbalance between LHS and RHS 6 %	Vehicle on Petrol HC Reading 40 PPM VOL
Vehicle on Petrol CO Reading 0.034 %			

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Vehicle Model - Registration Incorrect Model - Does Not Require Document	E CLASS	E400	

## Inspection Remarks:

FRONT LEFT FENDER REPAIRED/LEFT HEAD LIGHT BRACKET REPAIRED/& LEFT SIDE BULKHEAD BRACKET CRACK (OLD).

## Payment Details

Inspection Performed by 36785	Payment Method Cash	Transaction Number 13407738	Service Fees AED 170 Collected on 18/01/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Khawlah Abdo Saleh Moshen

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

