



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	30 Oct 2022, 11:39:27
Transaction Number	64775325 (CC10009)	Queue Number	614058



Chassis Number	SALLMAME4AA331918
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Vogue
Model Year	2010
Color	Grey
Mileage	80185 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
01.B Front Tyre	BOTH SIDE 2018 CRACKED	الاطار الامامي
02 Engine Condition		المحرك
02.A Other	ENGINE START SWITCH DAMAGED	اخرى
02.B Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظري
02.C Smoke	WHITE SMOKE	دخان
03 Interior Condition		الحاله الداخليه
03.A Other	MIDDLE TEA BOX SLIDING COVER DAMAGED	اخرى
03.B AC Condition	OK	المكيف
03.C Roof Ceiling	LOOSE	بطانه السقف
03.D Power Window Switch	REAR LEFT SIDE NOT WORKING	مفتاح النافذه
04 Lights		الاضاءة
04.A Fog light	NOT WORKING	كشاف الضباب
04.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
04.C Head Light	BOTH SIDE BRACKET DAMAGED	الاضاءة الرئيسية

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
05.B Road Test	NOT CHECK	فحص علي الطريق
05.C DIFFERENTIAL	REFITTED ,MINOR OIL LEAK	الدفرنشيل
06 Steering Condition		المقود
06.A Steering Oil	MINOR OILLEAK	زيت المقود
06.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
07 Suspension System		ممتص الصدمات
07.A Arms	BOTH SIDE LOWER ARM BUSHES CUT	ازرع
08 Seats Condition		المقاعد
08.A Seat Condition	FRONT RIGHT SIDE PORTION CUT	حالة المقاعد
09 Body		جسم المركبة
09.A Doors	RIGHT SIDE BOTH REPAINTED	أبواب
09.B Trunk	TRUNK AUTO NOT WORKING & PORTION REPAIRED,REPAINTED, TAIL GATE INNER COVER LOOSE	صندوق
09.C Bonnet	REPAIRED & REFITTED	غطاء المحرك
09.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,	الصبغ
09.E Sign of back accident		وجود مؤشر لحادث في الخلف
09.F Bumper	FRONT GRILL BOLTS PORTION DAMAGED	دعامية
09.G Fenders	FRONT BOTH SIDE REPAINTED REFITTED	مدكار
09.H Sign of front accident		وجود مؤشر لحادث في المقدمة
09.I Floor	FLOOR PORTION BOTH SIDE REINFORCEMENT DENT	الارضية
10 Chassis Condition		الشاسي
10.A Chassis	BOTH SIDE CHASSIS JOINT AREA LOWER EDGE MINOR DENT	الشاسيه
11 Engine Cooling System		نظام تبريد المحرك
11.A Radiator Condition	SIDE COVER REPAIRED	حالة المبرد
12 Brake Condition		الفرامل
12.A Brake Pedal	SPONGY	دواسة الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Car Check does not guarantee the vehicle's fitness for registration.

Test Certificate



Vehicle
Registration



✗ FAILED

Transfer Certificate :	67029402
Chassis No :	SALLMAME4AA331918
Vehicle Make :	RANGE ROVER
Vehicle Model :	VOGUE
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Gray
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	80189 Kms. ✗
Previous Odometer Reading :	253309 Kms.
Origin : Great Britain	Model Year : 2010
Gear Type : Automatic	Engine Size : 5600 CC
Engine No : 10071013005...	Horse 455
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 5
G. V. W. : 2850 Kgs.	Empty 2250 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17995954
Inspection Date :	01-11-2022
Certificate Print Date :	01-11-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	15 min 26 sec
Appointment Ref Number :	--
Start Time : 16:29	End Time : 16:44
Lane : 02	Token No. : 223
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle 3 %	Service brake imbalance on rear axle 30 %	Parking brake imbalance between LHS and RHS 16 %	Vehicle on Petrol CO Reading 7.19 %
Vehicle on Petrol HC Reading 846 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Vehicle on Petrol CO Reading	CO reading more than 4.5%	Major
Vehicle on Petrol HC Reading	HC reading more than 800ppm	Major
Vehicle on Petrol HC Reading	HC reading more than 800ppm	Major

Discrepancies	Old Value	New Value	Verified
Odometer Device Odometer Reading Change	Authorized	Replaced	
Engine Size Discrepancy in Engine Size	5600	5000	

Inspection Remarks: underneath oil wetness // right side engine mount minor leak //odometer roll back old km 253309



Odometer Record
Replace Events Date

01/11/2022

Payment Details

Inspection Performed by 34600 2151 2151	Payment Method Cash	Transaction Number 17995954	Service Fees AED 170 Collected on 01/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.