



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **25 May 2023, 15:14:58**  
 Transaction Number **14520613 (CC10006)** Queue Number **720391**



Chassis Number **KMHCT41B8EU600627**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Hyundai**  
 Model **Accent**  
 Model Year **2014**  
 Color **Grey**  
 Mileage **001 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING,OIL LEAK,REFITTED	حالة المحرك النظري
01.B Mount	BUSHES CUT	كرسي
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Head Light	LENS FADED,ALL LIGHTS NOT CHCKED.	الاضاءة الرئيسية
02.B Tail Light	LEFT SIDE COVER PORTION DAMAGED	الانارة
<b>03 Suspension System</b>		<b>ممتص الصدمات</b>
03.A Ball Joint	BOOT CUT	مفصل كروي
03.B Arms	LOWER ARM BUSHES CUT	ازرع
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Bumper	MISALIGN,PORTION DAMAGED.	دعامية
04.B Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
04.C Floor	UNDER FLOOR RUST PROOFED	الارضية
04.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED ,PORTION RUSTY	الصبغ
<b>05 Interior Condition</b>		<b>الحالة الداخلية</b>

DEFECT	REMARKS	
05.A AC Condition	NOT CHECKED	المكيف
05.B Mirror	CENTER MIRROR LOOSE	المرآيا
05.C Odometer reading	NOT CHECKED	قراءة عداد المسافات
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Rear Tyre	BOTH SIDE 2019 CRACKED,	الاطار الخلفي
07.B Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Road Test	NOT CHECKED	فحص علي الطريق
08.B Visual Gear Box Condition	MISSING	حالة الجير النظري
<b>09 Steering Condition</b>		<b>المقود</b>
09.A Axle	BOTH SIDE BAR, AXLE, AXLE CASE MISSING	اكسلات
09.B Tie Rod End	BOOT CUT	مؤخرة الرودادات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.