CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877838
Transaction Date	20 Oct 2026, 13:49:24
Site Name	840 - Emirates Auctions
Transaction Number	89692997 (CC10010) (CC10010)



Vehicle Details

Chassis Number	4T1BE32K84*******
Specification	Imported
Make	Toyota
Model	Camry
Model Year	2004
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED. BUMPER FRAME BEND .	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS END REPAIRED DENT GETTING RUSTY ,REAR EXTENSION END DENT GETTING RUSTY.	الشاسيه
02.B Chassis Number	VIN CHECEKD ONLY STICKER.	رقم القاعدة
03 Engine Condition		المحرك
03.A Mount	BUSHES CUT	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION CUT.	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Gear Box Mount	CRACKED	كرسي الجير
05.C Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	EXPIRED CRACKED DAMAGED.	الاطار الامامي
06.B Rear Tyre	EXPIRED CRACKED DAMAGED.	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES,	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
09.B Mirror	LOOSE FADED.	المرايا
09.C AC Condition	NOT CHECKED.	المكيف
09.D Dash Board	CRACKED PORTION LOOSE. BULGED.	لوحة القياده
09.E Roof Ceiling	PORTION LOOSE.	بطانه السقف
09.F Sun Visor	LOOSE.	حاجب الشمس
09.G Odometer reading	NOT CHECKED.	قراءة عداد المسافات
09.H Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
09.I Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم
09.J Gear Shifting Lever	KNOB WORN OUT.	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.