



### Test Certificate

|                     |                          |                    |                 |
|---------------------|--------------------------|--------------------|-----------------|
| Site Number         | : 840-TASJEEL EM AUCTION | Plate Code         | : 0             |
| Transaction Number  | : 18978197               | Plate Category     | : PRIVATE       |
| Transaction Date    | : 14 JAN 2020 14:04:43   | Plate Number       | : 7989 EA       |
| Queue Number        | : 134191                 | Import Doc. Ref.   | :               |
| Chassis Number      | : JN8AY2NY2D9057989      | Manufacturer/Model | : NISSAN/PATROL |
| Engine Number       | :                        | Model Year         | : 2013          |
| Vehicle Class       | : LIGHT VEHICLE          | Vehicle Color      | : WHITE         |
| Service / Indicator | : DSC AUCTION            |                    |                 |

### Statement of Vehicle Condition

| Defect   | Result  | Remarks                       |
|--|---|-------------------------------|
| AUTOMATIC TEST:                                |   |                               |
| 14 Exhaust Gas Test                            |   | الغاز العادم والكربون         |
| 14.01 - Exhaust Gas Test                       | Passed  | فحص الغاز العادم-الكربون      |
| VISUAL TEST:                                   |   |                               |
| 01 Lights                                      |   | الانوار                       |
| 01.04 - Head Lights                            | LENS FADED  | الانوار الامامية              |
| 02 Steering And Suspension System              |   | عجلة القيادة ونظام التوصيلات  |
| 02.13 - Stub Axle Assemblies, Boots            | BOTH SIDE INNER AXLE BOOT CRACK                         | المحور                        |
| 04 Tires Rims                                  |   | الاطارات والعجلات             |
| 04.01 - Front Left And Right Hands Tires       | TIRES DAMAGE(ROAD TEST NOT DONE)ENGINE & GEAR NOT CHECK | الاطارات الامامية             |
| 05 Body  |   | الهيكل                        |
| 05.01 - Rusty                                  | CHASSIS & SUSPENSION RUSTY                              | الصدأ                         |
| 05.02 - Paint                                  | BODY SCRATCH & DENT & BONNET PAINT PEEL OFF             | الصبغ                         |
| 05.09 - Front And Rear Windshields             | FRONT SPOT CRACK  | الزجاج الامامي والخلفي        |
| 06 General Items                               |   | الاشياء العامة                |
| 06.06 - Fog Light                              | RIGHT SIDE MISSING                                      | ضوء الضباب                    |
| 06.10 - Mirrors Side View                      | RIGHT SIDE MIRROR MISSING                               | المرآيا الجانبية              |
| 06.21 - Battery Condition                      | BATTERY DEAD  | حالة البطارية                 |
| 09 Auction                                     |   | الفحص الكامل                  |
| 09.06 - Chassis Ok                             | OK  | الشاصي جيد                    |
| 09.18 - A/C Not Cooling                        | NOT COOLING   | عطل في المكيف                 |
| 09.24 - Digital Display Damaged/Warning Lights | WARNING LIGHTS ON                                       | عطل في لوحة التحكم الالكتروني |
| 09.25 - Body Repainted                         | BODY PORTION REPAINTED                                  | أثر صبغ في المركبة            |

The Test Certificate Shows the test Result at the time of inspection only.