



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **06 May 2022, 11:34:39**
 Transaction Number **23175441 (CC10008)** Queue Number **312309**



Chassis Number **JTJMM7FX0H5168545**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Lexus**
 Model **GX 460**
 Model Year **2017**
 Color **White**
 Mileage **66995 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
02 Body		جسم المركبة
02.A Paint	BODY MINOR DENT ,SCRATCHES	الصبغ
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	OK	حالة الجير النظرى
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
05 Engine Condition		المحرك
05.A Visual Engine Condition	SIGN OF MINOR OIL LEAK	حالة المحرك النظرى
06 Suspension System		ممتص الصدمات
06.A Arms	FRONT LOWER ARM BUSH CRACKED	ازرع

DEFECT

REMARKS

07 Chassis Condition

الشاسي

07.A Chassis

OK

الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.