CAR CHECK

# شهادة فحص مركبة
# Vehicle Test Certificate

| | |
|---|---|
| Queue Number | 2944994 |
| Transaction Date | 05 Nov 2026, 16:44:51 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 97801559 (CC10013) (CC10013) |




## Vehicle Details

| | |
|---|---|
| Chassis Number | KNAMB76319******* |
| Specification | GCC Specification |
| Make | Kia |
| Model | Carnival |
| Model Year | 2009 |
| Color | White |
| Mileage | N/A NA |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 6 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Paint | BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY | الصبغ |
| 01.B Rusty | UNDER BODY PARTS ,SUSPENSION GETTING RUSTY | صدأ |
| 01.C Floor | UNDER FLOOR PORTION DENTS, MUDDY | الارضية |
| 01.D Bumper | MISALIGN, PORTION DAMAGED | دعامية |
| 01.E Roof | CARRIER COVER PART MISSING | السقف |
| 01.F Trunk | NOT OPEN | صندوق |
| 01.G Fuel Tank | DAMAGED LEAK | خزان الوقود |
| 01.H Sign of front accident | FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED | وجود مؤشر لحادث في المقدمة |
| 01.I Sign of back accident | BACK PANEL, QUATER PANEL, COMPARTMENT REPAIRED | وجود مؤشر لحادث في الخلف |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | FRONT RIGHT SIDE CHASSIS BULK HEAD , MUDDY DIRTY PORTION GETTING RUSTY | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK OIL PAN DAMAGED . PARTS RUSTY KEY MISSING | الحالة النظريه للمحرك |
| **04 Seats Condition** | | المقاعد |
| 04.A Seat Condition | PORTION WORN OUT CRACK | حالة المقاعد |

| Condition | Remarks | الحالة |
|---|---|---|
| **05 Exhaust System** | | نظام العادم |
| 05.A Other | DENT | اخري |
| **06 Transmission Condition** | | الجير |
| 06.A Gear Box Visual Condition | NOT CHECKED REFITTED OIL LEAK PARTS RUSTY | الحالة النظريه للجير |
| 06.B Road Test | NOT CHECKED | فحص علي الطريق |
| **07 Tires and Rims Condition** | | الاطارات |
| 07.A Front Tyre | 2023 DRY CRACK | الاطار الامامي |
| 07.B Rear Tyre | 2023 DRY CRACK | الاطار الخلفي |
| 07.C Spare Tire &Tools | SPARE MISSING | الاطار الاحتياطي و العدة |
| **08 Lights** | | الاضاءة |
| 08.A Head Light | LENS FADED, ALL LIGHTS NOT CHECKED | الاضاءة الرئيسية |
| **09 Brake Condition** | | الفرامل |
| 09.A Disc&Drum | RUSTY | دسك وطنابير الفرامل |
| **10 Suspension System** | | ممتص الصدمات |
| 10.A Shock Absorber | LEAK | ممتص الصدمات |
| 10.B Arms | LOWER ARM BUSHES CUT | ازرع |
| 10.C Ball Joint | BOOT CUT | مفصل كروي |
| 10.D Stabilizer Bar And Link Rod | BOOT CUT | عمود التوازن و مثبت عمود التوازن |
| **11 Steering Condition** | | المقود |
| 11.A Tie Rod End | BOOT CUT | مؤخرة الرودات |
| **12 Interior Condition** | | الحاله الداخليه |
| 12.A Other | INTERIOR PARTS RUSTY, SIGN OF FLOODED | اخري |
| 12.B AC Condition | NOT CHECKED | المكيف |
| 12.C Roof Light | MISSING | أنارة السقف |
| 12.D Dash Board | GETTING FADED PORTION WORN OUT CRACK | لوحة القياده |
| 12.E Roof Ceiling | PORTION WORN OUT | بطانه السقف |
| 12.F Odometer reading | NOT CHECKED | قراءة عداد المسافات |
| 12.G Door Panel | PORTION WORN OUT | لوحة بطانة الباب |
| 12.H Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 12.I Gear Shifting Lever | KNOB WORN OUT | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**