

Queue Number

2241942

Transaction Date

09 Mar 2026, 14:50:07

Site Name

840 - Emirates Auctions

Transaction Number

60204668 (CC10018) (CC10018)



Vehicle Details

Chassis Number	JN6BE6BS3D*****
Specification	GCC Specification
Make	Nissan
Model	Urvan
Model Year	2013
Color	White
Mileage	838818 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES, PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	RUNNING BOARD DENT	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Fuel Tank	DENT	خزان الوقود
01.F Sign of front accident	BUMPER FRAME, FENDER FRAME, FIREWALL REPAIRED	وجود مؤشر لحادث في المقدمة
01.G Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS END, CROSSMEMBER REPAIRED, REAR BOTH SIDE CHASSIS EXTENSION END DENT	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED, REFITTED, OIL LEAK, PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد
---------------------	-----------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED, REFITTED, OIL LEAK, PARTS GETTING RUSTY	الحالة النظرية للجير
05.B DIFFERENTIAL	OIL LEAK	الدفرنشل
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022, DRY CRACKED, WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022, DRY CRACKED, WORN OUT	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE DAMAGED	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Leaf Spring	BUSH CRACKED	مفصل كروي عمود التوازن و مثبت عمود التوازن
08.C Ball Joint	BOOT CUT	
08.D Stabilizer Bar And Link Rod	BUSH CRACKED	
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	NOT CHECKED	المكيف
10.C Floor Matting	PORTION DAMAGED	فرش الأرضيه
10.D Dash Board	WORN OUT	لوحة القيادة
10.E Door Panel	WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae