

Queue Number 2845158

Transaction Date 07 Oct 2026, 16:54:33

Site Name
840 - Emirates AuctionsTransaction Number
56343470 (CC10026) (CC10026)

Vehicle Details

Chassis Number 2C3CDXCT5H*****
 Specification Imported
 Make Dodge
 Model Charger
 Model Year 2017
 Color Red
 Mileage N/A Miles
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة
---------	-------------

01.A Fenders	FRONT RIGHT SIDE REPAINTED ,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED , FRONT PORTION REPAIRED , REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	BOTH SIDE MIDDLE FLOOR, RUNNING BOARD REPAIRED, DENT , MUDDY, PORTION RUSTY	الارضية
01.F Bumper	MISALIGN , DAMAGE FIX BY SCREW , PORTION FADED	دعامية
01.G Windshield	FRONT SPOT CRACK & DENT	زجاج
01.H Bonnet	REFITTED , CARBON MODIFIED PAINT NO CHECK , RIGHT SIDE GRILL DAMAGE , MISALIGN	غطاء المحرك
01.I Trunk	NOT OPENING	صندوق
01.J Sign of front accident	BUMPER FRAME , INNER FENDER FRAME , RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition	الشاسي
----------------------	--------

02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED DENT BEND REPAIRED , OILLY MUDDY	الشاسيه
--------------	---	---------

03 Engine Condition	المحرك
---------------------	--------

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition	المقاعد
--------------------	---------

04.A Seat Condition	PORTION WORN OUT , FRONT RIGHT SIDE SEAT SIDE PANEL DAMAGE	حالة المقاعد
---------------------	--	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Modification	EXHUST PIPE CUT REWELDED , MODIFIED	تعديلات
05.B Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024 CRACK WORN OUT	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2021 EXPIRED DAMAGE , RIGHT SIDE 2025 CRACK	الاطار الخلفي
07.C Rims Condition	DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08.B Fog light	LEFT SIDE HOUSING LOOSE , RIGHT SIDE DAMAGE	كشف الضباب
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطناير الفرامل
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE PANEL PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
10.B AC Condition	NOT CHECK , REAR ADJUSTABLE SWICTH DAMAGE	المكيف
10.C FLOOR Matting	DIRTY	فرش الأرضيه
10.D Door Panel	DAMAGE	لوحة بطانة الباب
10.E Gear Shifting Lever	KNOB PORTION WORN OUT	ذراع نقل السرعات
10.F Engine Start Button	FADED	زر تشغيل المحرك
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae