CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3002712
Transaction Date	17 Nov 2026, 16:51:48
Site Name	840 - Emirates Auctions
Transaction Number	88503997 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WP0ZZZ98Z3*******
Specification	Imported
Make	Porsche
Model	Boxster
Model Year	2003
Color	Red
Mileage	140633 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Rusty	UNDER BODY PASRT ENGINE GEAR SUSPENSION RUSTY	صدأ
01.D Floor	FLOOR RUST PROOFED, CHASSIS COVERED	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Roof	CONVERTIBLE ROOF FABRIC MINOR CUT	السقف
01.G Bonnet	SHOCK NOT WORKING	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE RUSTY, PARTS REFITTED	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT COVER PORTION CRACKED	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	RUSTY	اخري
06 Transmission Condition		الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	RUSTY, PARTS REFITTED	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	BOTH SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
09 Suspension System		ممتص الصدمات
09.A Suspension Subframe	REAR REFITTED	
09.B Other	SUSPENSION REFITTED	اخري
10 Steering Condition		المقود
10.A Axle	REAR BOOT CUT	اكسلات
11 Interior Condition		الحاله الداخليه
11.A AC Condition	NOT WORKING	المكيف
11.B Sun Visor	BOTH SIDE COVER MIRROR DAMAGED,MISSING	حاجب الشمس
11.C Door Panel	PORTION WORN OUT	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae