

Queue Number 2653437

Transaction Date 17 Aug 2026, 16:29:08

Site Name
840 - Emirates AuctionsTransaction Number
98274379 (CC10008) (CC10012)

Vehicle Details

Chassis Number	JN8AE2KPXD*****
Specification	Imported
Make	Nissan
Model	Quest
Model Year	2013
Color	Silver
Mileage	50284 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REFITTED , RIGHT SIDE SKIRT MISSING	مذكّر
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Doors	FRONT RIGHT SIDE SKIRT LOOSE , REAR LEFT SIDE AUTO NOT WORKING	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Bumper	REAR BOTH SIDE REFLECTOR COVER MISSING,MISALIGN FRONT STRIP MISSING	دعامية
01.F Windshield	FRONT CRACK	زجاج
01.G Bonnet	REFITTED	غطاء المحرك
01.H Trunk	REFITTED , BUTTON DAMAGED , AUTO NOT WORKIN FROM TRUNK	صندوق
01.I Sign of back accident		وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY CHECKED VISIBLE AREA / OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK ,REFITTED MISFIRING ABNORMAL NOISY ,PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER , DRIVER SEAT ADJUSTMENT SWITCH PORTION MISSING , SIDE COVER LOOSE	حالة المقاعد
---------------------	--	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL WET REFITTED PARTS GETTING RUSTY ,DELAY SHIFTING	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	FRONT RIGHT , REAR LEFT SIDE HUB COVER MISSING	حالة الجنوط
07 Interior Condition		الحالة الداخلية
07.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF WATER FLOODED	اخرى
07.B AC Condition	OK	المكيف
07.C Dash Board	CRACKED ,PORTION MELTED	لوحة القيادة
07.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.E Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae