



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	21 Jun 2022, 16:51:04
Transaction Number	94805420 (CC10006)	Queue Number	312309



Chassis Number	WBAKU2101H0V51702
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	X6 - 35
Model Year	2017
Color	White
Mileage	105864 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Engine Condition		المحرك
01.A Visual Engine Condition	OK	حالة المحرك النظري
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	OK	حالة الجير النظري
03 Body		جسم المركبة
03.A Floor	UNDER BODY COVERD & ONLY VISABLE AREA CHECK	الارضية
03.B Paint	BODY PORTION REPAINTED,MINOR DENT,SCRATCHES	الصبغ
03.C Bonnet	REFPAINTED,REFITTED	غطاء المحرك
03.D Fenders	FRONT FENDER FIBER PAINT CANNOT CHECK	مدكار
04 Interior Condition		الحاله الداخليه
04.A AC Condition	OK	المكيف
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي

DEFECT

REMARKS

06 Chassis Condition

الشاسي

06.A Chassis

VISABLE AREA OK

الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.