



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	12 Jan 2023, 16:57:13
Transaction Number	40920984 (CC10009)	Queue Number	656636



Chassis Number	WBA3N3107EF709850
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	428
Model Year	2014
Color	Silver
Mileage	75198 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Chassis Condition		الشاسي
01.A Chassis	CHECKED VISIBLE AREA ONLY /OK	الشاسيه
02 Interior Condition		الحاله الداخليه
02.A AC Condition	OK	المكيف
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2021/2020	الاطار الخلفي
03.C Rims Condition	SCRATCHES	حالة الجنوط
04 Steering Condition		المقود
04.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
05 Engine Condition		المحرك
05.A Mount	MOUNT RUBBER CRACKED	كرسي
05.B Visual Engine Condition	MINOR OIL LEAK ,ABNORMAL NOISY	حالة المحرك النظري
06 Suspension System		ممتص الصدمات
06.A Arms	LOWER ARM BUSHES CUT	ازرع

DEFECT	REMARKS	
06.B Ball Joint	BOOT CUT	مفصل كروي
07 Body		
07.A Paint	BODY MINOR DENT SCRATCHES	الصبغ
07.B Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA	الارضية
08 Transmission Condition		
08.A Visual Gear Box Condition	SIGN OF MINOR OIL LEAK	حالة الجير النظري
08.B Road Test	NOT CHECK	فحص علي الطريق

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.