



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>26 May 2023, 17:04:06</b>
Transaction Number	<b>22282365 (CC10008)</b>	Queue Number	<b>727424</b>



Chassis Number	<b>JN1FN61C09W098130</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Sunny</b>
Model Year	<b>2009</b>
Color	<b>White</b>
Mileage	<b>258551 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Bumper	BUMPER PORTION DAMAGED&FRONT BUMPER FRAME ,CROSH BOX BEND	دعامية
01.B Bonnet	REFITTED	غطاء المحرك
01.C Paint	BODY REPAINTED,PORTION REPAIRED,DENT,SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
01.D Fenders	FRONT REFITTED	مدكار
01.E Sign of front accident		وجود مؤشر لحادث في المقدمة
01.F Pillars	RIGHT SIDE A/PILLAR INNER POST COVER MISSING	القوائم
01.G Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
01.H Floor	PORTION DENT	الارضية
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	FRONT RIGHT SIDE CHASSIS DAMAGED& LEFT SIDE END BEND	الشاسيه
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A Other	CENTER CONSOLE BOX DAMAGED	اخرى
03.B Door Panel	PORTION DAMAGED	لوحة بطانة الباب

DEFECT	REMARKS	
03.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
03.D AC Condition	NOT CHECK	المكيف
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
04.B Gear Box Mount	CRACKED	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,OIL LEAK	حالة المحرك النظري
05.B Mount	CRACKED	كرسي
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Coil Spring	HEATED	ياي حلزوني
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2021,LEFT SIDE PUNCTURE	الاطار الخلفي
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Tail Light	RIGHT SIDE DAMAGED	الانارة
08.B Head Light	LENS FADED,LEFT SIDE BRACKET BROKEN	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.