CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906086
Transaction Date	27 Oct 2026, 13:00:43
Site Name	840 - Emirates Auctions
Transaction Number	49358509 (CC10021) (CC10021)



Vehicle Details

Chassis Number	RKLBC42E6B*******
Specification	GCC Specification
Make	Toyota
Model	Corolla
Model Year	2011
Color	White
Mileage	248842 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE FIX BY SCREW	دعامية
01.E Sign of back accident	BACK PANEL, QUATER PANEL, BUMPER FRAME REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY , PORTION DENT	الشاسيه
03 Engine Condition		المحرك
03.A Other	ENGINE UPPER COVER CRACK	اخري
03.B Engine Visual Condition	NO CONTINUE STARTING , PARTS REFITTED GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED, PARTS REFITTED GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للجير
06 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE CRACK ,WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES , GETTING RUSTY	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	PORTION CRACK	الضوء الخلفي
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CRACK	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE PANEL WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
10.B Mirror	LEFT SIDE VIEW MIRROR DAMAGE & RIGHT SIDE VIEW MIRROR GLASS CRACK	المرايا
10.C AC Condition	NOT CHECK	المكيف
10.D Dash Board	PORTION DAMAGE , CONTROL SWICTH PANEL DAMAGE	لوحة القياده
10.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر

wecare@carscheck.ae