



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Jan 2023, 17:01:00
Transaction Number	21648149 (CC10006)	Queue Number	657761



Chassis Number	JN1FN61C05W501078
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Sunny
Model Year	2005
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Chassis Condition		الشاشي
01.A Chassis	REAR RIGHT SIDE CHASSIS EXTENSION REPAIRED.	الشاشيه
02 Suspension System		ممتص الصدمات
02.A Arms	LOWER ARM BUSHES CRACKED .	ازرع
02.B Shock Absorber	LEAK .	ممتص الصدمات
03 Steering Condition		المقود
03.A Steering Oil	OIL LEAK .	زيت المقود
03.B Axle	BOOT CUT .	اكسلات
04 Interior Condition		الحاله الداخليه
04.A AC Condition	NOT CHECKED ,GRILL PORTION DAMAGED.	المكيف
04.B Sun Visor	MISSING.	حاجب الشمس
04.C Dash Board	DAMAGED .	لوحة القيادة
04.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
04.E Odometer reading	NOT CHECKED .	قراءة عداد المسافات
05 Lights		الاضاءة

DEFECT	REMARKS	
05.A Head Light	LENS FADED ,ALL IGH T NOT CHECKED .	الاضاءة الرئيسية
06 Transmission Condition		الجير
06.A Visual Gear Box Condition	REFITTED OIL LEAK .	حالة الجير النظرى
06.B Road Test	NOT CHECKED .	فحص علي الطريق
07 Body		جسم المركبة
07.A Paint	BODY PORTION REPAIRED ,REPAINTED .MINOR DENTS SCRATCHES PORTION FADED ,PORTION RUSTY .	الصبغ
07.B Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY .	صدأ
07.C Doors	BEEDING BOTH SIDE MISSING .	أبواب
07.D Bumper	MISALIGN PORTION DAMAGED .	دعامية
07.E Sign of back accident		وجود مؤشر لحادث في الخلف
07.F Other	FRONT BUMPER FRAME ,FEDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.	اخرى
07.G Floor	BACK PANEL SPARE WHEEL HOUSING ,QUARTER PANEL REPAIRED ,BACK PANEL DENT .	الارضية
07.H Trunk	NOT OPEN .	صندوق
07.I Windshield	FRONT CRACKED .	زجاج
07.J Sign of front accident		وجود مؤشر لحادث في المقدمة
08 Engine Condition		المحرك
08.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,REFITTED OIL LEAK .	حالة المحرك النظرى
09 Tires and Rims Condition		الاطارات
09.A Front Tyre	BOTH SIDE 2020 CRACKED .	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2020 CRACKED .	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.