

Queue Number 2823301

Transaction Date 06 Oct 2026, 15:01:02

Site Name
840 - Emirates AuctionsTransaction Number
37776791 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WDDUG8CB6E*****
Specification	GCC Specification
Make	Mercedes
Model	S 500
Model Year	2014
Color	Black
Mileage	132155 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED , REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
01.E Floor	FLOOR COMPLETELY COVERED MUDDY NOT VISIBLE	الارضية
01.F Bumper	MISALIGN , PORTION CRACK , GRILL PORTION CRACK	دعامية
01.G Windshield	FRONT CRACKED	زجاج
01.H Bonnet	REPAINTED , REFITTED	غطاء المحرك
01.I Trunk	REPAINTED PORTION REPAIRED , REFITTED , MISALIGN	صندوق
01.J Sign of back accident	BACK PANEL QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
01.K Vehicle Model	S 500	طراز المركبة

02 Chassis Condition

الشاسي

02.A Chassis	OK,	الشاسيه
--------------	-----	---------

03 Engine Condition

المحرك

03.A Other	ENGINE OIL CAP PORTION DAMAGED	اخرى
03.B Engine Visual Condition	MINOR OIL LEAK PARTS REFITTED, ABNORMAL NOISY SHAKING GETTING RUSTY MUDDY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	FRONT BOTH SIDE BACK COVER LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED FULLY MUDDY GETTING RUSTY MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026 , RIGHT SIDE WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES , HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	RIGHT SIDE PORTION CRACK	الضوء الخلفي
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Other	SUSPNSION REFITTED	اخرى
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY , CENTER CONSOLE BOX WORN OUT , COVER PORTION MISSING	اخرى
09.B AC Condition	OK	المكيف
09.C Power Window Switch And Glass	REAR LEFT SIDE SWITCH PORTION MISSING	مفتاح النافذه و الزجاج
09.D Audio	SCREEN PORTION FADED	صوتيات
09.E Sun Visor	RIGHT SIDE MIRROR LIGHT NOT WORK , COVER CRACK	حاجب الشمس
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.G Sunroof	COVER SWITCH MISSING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae