



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>17 Nov 2022, 17:51:26</b>
Transaction Number	<b>83359427 (CC10009)</b>	Queue Number	<b>625137</b>



Chassis Number	<b>WBAKR010500X67319</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>BMW</b>
Model	<b>X5</b>
Model Year	<b>2017</b>
Color	<b>White</b>
Mileage	<b>146795 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>Imported</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK	المكيف
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
03.B Smoke	MINOR BLACK SMOKE	دخان
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
04.B Road Test	NOT CHECKED	فحص علي الطريق
04.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>05 Body</b>		<b>جسم المركبة</b>
05.A Paint	BODY MINOR DENT SCRATCHES	الصبغ
05.B Fenders	UNDER FLOOR FENDER CHASSIS FRAME FULLY COVERED CHECKED VISIBLE AREA	مدكار

DEFECT	REMARKS	
<b>06 Chassis Condition</b>		الشاصي
06.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY OK	الشاسيه
<b>07 Suspension System</b>		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CUT	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
<b>08 Lights</b>		الاضاءة
08.A Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
<b>09 Steering Condition</b>		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.