CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2900315
Transaction Date	23 Oct 2026, 14:39:17
Site Name	840 - Emirates Auctions
Transaction Number	86767970 (CC10008) (CC10025)

Vehicle Details

Chassis Number	JTJHT00W74*******
Specification	Imported
Make	Lexus
Model	LX 470
Model Year	2004
Color	White
Mileage	193624 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION RUSTY ,PAINTED ,FOOT STEP BOARD LOOSE	الارضية
01.D Bumper	MISALIGN , HOOK COVER MISSING	دعامية
01.E Bonnet	REFITTED SHOCK WEAK	غطاء المحرك
01.F Trunk	REFITTED	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME RUSTPROOFED PORTION RUSTY PORTION BULGED DENT .	الشاسيه
02.B Other	REAR MIDDLE CROSS MEMBER RUSTY HOLE	اخري
03 Engine Condition		المحرك
03.A Other	TOP COVER DAMAGED	اخري
03.B Engine Visual Condition	OIL LEAK ,REFITTED ,PART ,PAINTED ,PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED ,PAINTED	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	REAR MISSING	ازرع المساحات والشفرات
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	FRONT MINOR OIL LEAK ,REAR BOTH SIDE COVER DENT,RUSTY HOLE	ممتص الصدمات
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY , INTERIOR MODIFIED	اخري
10.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING PROPERLY	المرايا
10.C AC Condition	OK	المكيف
10.D FLoor Matting	EXTRA PLASTIC COVER	فرش الأرضيه
10.E Roof Ceiling	MODIFIED	بطانه السقف
10.F Door Panel	WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT,PLAY	عجلة القيادة وازرار التحكم
10.H Sunroof	NOT WORKING	فتحت سقف
11 Engine Cooling System		نظام تبريد المحرك
11.A Radiator Condition	COOLANT LEAK	حالة المبرد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.