

Queue Number

2463221

Transaction Date

17 Jun 2026, 12:00:34

Site Name

840 - Emirates Auctions

Transaction Number

11089283 (CC10010) (CC10010)



Vehicle Details

Chassis Number

KMHEB41C1B*****

Specification

GCC Specification

Make

Hyundai

Model

Sonata

Model Year

2011

Color

Silver

Mileage

N/A Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES,PORTION FADED,PORTION RUSTY,SIGN OF HAILSTORM.	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY ,.	الارضية
01.D Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.E Bonnet	SHOCK WEAK	غطاء المحرك
01.F Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT ,CROSS MEMBER REPAIRED	وجود مؤشر لحادث في المقدمة
01.G Sign of back accident	BACK PANEL , COMPARTMENT, QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIRPAIRED DENT GTTING RUSTY ,CHASSIS COVERED OILY MUDDY ,CHECKED ONLY VISIBLE AREA.	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER.	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY.	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	COVER PORTION CUT	حالة المقاعد
---------------------	-------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY.	الحالة النظرية للجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحالة الداخلية
11.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED & CENTER CONSOLE BOX COVER CRACKED	اخرى
11.B Mirror	CENTER MIRROR PORTION FADED	المرآيا
11.C AC Condition	NOT CHECKED	المكيف
11.D Dash Board	PORTION WORN OUT	لوحة القيادة
11.E Roof Ceiling	PORTION LOOSE	بطانه السقف
11.F Odometer reading	NOT CHECKED	قراءة عداد المسافات
11.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae