

Queue Number 2894169

Transaction Date 21 Oct 2026, 16:44:49

Site Name
840 - Emirates AuctionsTransaction Number
30330882 (CC10013) (CC10011)

Vehicle Details

Chassis Number	4JGFB5KB7L*****
Specification	Imported
Make	Mercedes
Model	GLE 450
Model Year	2020
Color	White
Mileage	110880 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	LEFT SIDE BOTH REPAIRED REPAINTED SKIRT MISALIGN,FRONT RIGHT SIDE REPAINTED PORTION REPAIRED,FRONT BOTH REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAIRED REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COMPLETELY COVERED FOR FULL INSPECTION REMOVE INNER FENDER UNDER FLOOR COVER FOR RECHECK	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	LEFT SIDE ROOF RAIL REPAIRED	السقف
01.H Bonnet	REPAIRED REPAINTED	غطاء المحرك
01.I Pillars	LEFT SIDE A/PILLAR OUTER PANEL REPAIRED	القوائم
01.J Other	UNDER FLOOR PARTS WATER EFFECTIVE	اخرى
01.K Trunk	REPAINTED REPAIRED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------	-----------------------

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Belt	REAR LEFT SIDE NOT WORKING / RIGHT SIDE STUCK	حزام الأمان
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JEKRING , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES DRY CRACK	ازرع
08 Interior Condition		الحالة الداخلية
08.A Other	CENTER CONSOLE BOX PANEL PORTION WORN OUT,CUP HOLDER LEFT SIDE LOCK DAMAGED INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK	المكيف
08.C Dash Board	MINOR SCRATCHES	لوحة القيادة
08.D Roof Ceiling	PORTION WORN OUT DAMAGED	بطانة السقف
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.F Engine Start Button	WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae